

## Menu


HISTORY FILE MAP for year 2004

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



073.01:45-01:52 7m RT 1024bps data lost due to long BRC from 4096bps to 1024bps at DSS63. Bad weather also present. No DR was raised.

071.06:03-06:19 17m RT 1024bps data lost during long transition from 1-way to 2-way at DSS24. TLP (Telemetry Processor) problem. DR G104144 refers.